

Field Termination Plug User Guide

FP

1

Copper Foil Tape
30mm
10mm

SR-A Ø9.0
or
SR-B Ø7.3

2

Boot
Cable

3

30mm Min.
10mm
S/FTP or U/FTP.F/UTP

4

30mm Min.
10mm
Copper Foil Tape

5

30mm Min.
10mm
Copper Foil Tape
Wrapped up

6

7

5-8mm Max.

8

9

Cut front row wires flush

10

Cut rear row wires flush

11

0.2mm Max.

12

KEY

13

1

14

2
Click
3

15

OK NG

16

Legend
W White
G Green
O Orange
BL Blue
BR Brown

1	2	3	4	5	6	7	8
W-G	G	W-O	BL	W-BL	O	W-BR	BR

Pin assignment T568A

1	2	3	4	5	6	7	8
W-O	O	W-G	BL	W-BL	G	W-BR	BR

Pin assignment T568B

	Solid	Stranded	Cable (O.D.)
C6A	23~26AWG	23~26AWG	5.6~8.5mm
C8	22~24AWG	22~24AWG	5.6~8.5mm